

# *Energy Solutions*



Above photo: Uncoated after 4 months

## Buckeye Paper Mill, N. Florida

Below Photo: Coated with ADSIL after 24 months

